

M8x40 - 1ks
M10x30 - 8ks
M12x70 - 2ks (A)
M12x90 - 2ks (I)
M12x19 - 4ks (C)



MS8 - 1ks



M10 - 4ks
M12 - 2ks (A, I)



P8 - 1ks
PP10 - 8ks
PP12 - 2ks (A, I)
PP12 - 4ks (C)




M10Z/17 - 2ks




PR14 - 1ks

C




M12x19 - 4ks



M12x90 - 2ks

I



DETAIL

