

Skid Plate Accessory Installation manual

700B

Model year:

FMC 2021 (700B)

Vehicle Code:

Part Number:

PW41A-60000 (700B)



Weight:


Steel: 16,15 kg








Installation Time:


30 min

PW41A-60000 (700B)




PW41A-60000-60

B  Cage nut M62x	C  Ø8 4x	D  Spacer sleeve2x	E TBC. Maybe re-use x3 OE bolts. In this case, need to include x1 additional bolt in kit.  Bolt M8x164x
F  Bolt M8x302x	G  2x		




12 mm
13 mm




1

Z1




M8

Z2



M8

Z3



M6




see repair manual




VJA300L-GMUZZW	7x	4x	2x
FJA300L-GMUZYW	7x	3x	2x
VJA300L-(except VJA300L-GMUZZW)	7x	4x	2x
FJA300L-(except FJA300L-GMUZYW)	7x	2x	2x
GRJ300L-GNTAKV	7x	-	2x


VJA300L-GMUZZW




FJA300L-GMUZYW




VJA300L-(except VJA300L-GMUZZW)






FJA300L-(except FJA300L-GMUZYW)






GRJ300L-GNTAKV






2




Torque moment is unknown




3




	Z2   M8
VJA300L-GMUZZW	4x
FJA300L-GMUZYW	3x
VJA300L-(except VJA300L-GMUZZW)	4x
FJA300L-(except FJA300L-GMUZYW)	2x
GRJ300L-GNTAKV	-


VJA300L-GMUZZW




FJA300L-GMUZYW




VJA300L-(except VJA300L-GMUZZW)




FJA300L-(except FJA300L-GMUZYW)




GRJ300L-GNTAKV







VJA300L-GMUZZW




VJA300L-(except VIA300L-GMUZZW)



FJA300L-GMUZYW



GRJ300L-GNTAKV



FJA300L-(except FJA300L-GMUZYW)