


M10x90 - 4ks
M12x70 - 2ks (A)
M12x19 - 3ks (C)
M12x21 - 1ks (C)



M10 - 4ks
M12 - 2ks (A)



PP10 - 2ks
PP12 - 8ks (A)
PP12 - 10ks (C)




4ks





R18x2,5-54 - 4ks

C




M12x19 - 3ks
M12x21 - 1ks

Galina®



M10x90



M12x70