





M10x30 - 6ks
M12x70 - 2ks (A)
M12x19 - 3ks (C)
M12x22 - 1ks (C)



M10 - 6ks
M12 - 2ks (A)



PP10 - 6ks
PP12 - 2ks (A)
PP12 - 4ks (C)



P11 - 2ks

C

