

M10x30 - 2ks
M10x40 - 2ks
M12x30 - 2ks
M12x90 - 2ks (I)
M12x19 - 3ks (C)
M12x21 - 1ks (C)



M10 - 2ks
M12 - 4ks (I)
M12 - 2ks (C)




PP10 - 4ks
PP12 - 4ks (I)
PP12 - 6ks (C)




P10 - 4ks

C



M12x19 - 3ks
M12x21 - 1ks

DETAIL



Galina®

