




M10x1,25x35 - 4ks
M10x1,25x70 - 2ks
M12x70 - 2ks (A)
M12x19 - 3ks (C)
M12x21 - 1ks (C)



M12 - 2ks (A)




PP10 - 6ks
PP12 - 4ks (A)
PP12 - 6ks (C)




P11 - 6ks

C



M12x19 - 3ks
M12x21 - 1ks

DETAIL 1



DETAIL 2

