



M10x1,25x25 - 6ks
M10x30 - 2ks
M10x35 - 2ks
M12x70 - 2ks (A)
M12x19 - 3ks (C)
M12x21 - 1ks (C)



M10 - 4ks
M12 - 2ks (A)



PP10 - 10ks
PP12 - 2 ks (A)
PP12 - 4 ks (C)



P10 - 4ks

C

