

M8x40 - 1ks
M10x40 - 4ks
M12x70 - 2ks
(M12x19 - 4ks)




M8 - 1ks
M12 - 2ks (0ks)



PP8 - 1ks
PP10 - 4ks
PP12 - 2ks (4ks)




M10Z/17 - 2ks






P10 - 5ks

C



DETAIL



A