

M8x20 - 2x
M8x30 - 3x
M12x35 - 6x
M14x100 - 8x
M12x70 - 2x (A)
M12x90 - 2x (I)
M12x19 - 3x (C)
M12x21 - 1x (C)



M8 - 5x
M12 - 6x (A, I)
M12 - 4x (C)




P14 - 8x

PP8 - 5x
PP14 - 8x
PP12 - 8x (A, I)
PP12 - 10x (C)




P8 - 3x
P12 - 2x




BP 360 - 2x


C



M12x19 - 3x
M12x21 - 1x



M12x90 (10.9) - 2x
110 Nm



M12x70 - 2x

vyrezať držiak výfuku z výstuhy nárazníka

cut the exhaust holder from the bumper reinforcement

I

IC 325 0 1

LAND ROVER DISCOVERY SPORT
Kód: R1075(A,I,C) - 14. 7. 2022

A