



M8x40 - 1ks
M10x35 - 4ks
M12x35 - 4ks
M12x70 - 2ks
(M12x19 - 4ks)



M8 - 1ks
M10 - 4ks
M12 - 4ks





P10 - 4ks



PP8 - 1ks
PP10 - 4ks
PP12 - 6ks

C



A