



M8x40 - 1ks
M10x35 - 4ks
M12x35 - 4ks
M12x70 - 2ks (A)
M12x19 - 4ks (C)




M8 - 1ks
M12 - 4ks (A)
M12 - 2ks (C)



PP10 - 4ks
PP12 - 6ks (A)
PP12 - 8ks (C)



P8,5 - 1ks




M10Z - 4ks



1ks

C



M12x19 - 4ks

DETAIL

